

CS Part 12 Scaffold and Scaffold Platforms has Been Amended Due to the ARC Report to ORR

STANDARD	RULE NUMBERS	MIOSHA IMPLEMENTATION STRATEGY
CS Part 12 Scaffold and Scaffold Platforms Effective April 11, 2013 Strike-Bold Draft	R 408.41210	The requirement for lumber standards will be addressed by Rules 1217, 1210(8), or a general duty violation with reference to the applicable ANSI Standard.
	R 408.41211	The hazards associated with the rescinded rule will be addressed by Rule 1217(9).
	R 408.41215	The hazards associated with the rescinded rules will be addressed by Rules 1214(1) and 1214(3).
	R 408.41217	The hazards associated with the rescinded rules will be addressed by Rules 1217(1), 1217(5) and 2159(1).
	R 408.41221	The hazards associated with the rescinded rules will be addressed by Rule 1210(3).
	R 408.41222	The hazards associated with the rescinded rule will be addressed by Rule 1210(8) and Appendix A.
	R 408.41224	The hazards associated with the rescinded rule will be addressed by Rules 1210(1) and 1210(3).
	R 408.41225	The rules for horse scaffolds were amended to the OSHA equivalent.
	R 408.41226	The rules for bricklayer's square scaffolds were amended to the OSHA equivalent.
	R 408.41227	The hazards associated with the rescinded rules will be addressed by Rules 1210(3) and 1217(1).
	R 408.41228	The hazards associated with the rescinded rules will be addressed by Rules 1210(1) and 1210(3).
	R 408.41231	The hazards associated with the rescinded rules will be addressed by Rules 1229(2), 1229(3), and 1229(15)(e).
	R 408.41233	The hazards associated with the rescinded rules will be addressed by Rules 1210(3) and 1210(6).
	R 408.41234	The hazards associated with the rescinded rules will be addressed by Rules 1213(3) and 1210(3).
	R 408.41235	The hazards associated with the rescinded rules will be addressed by Rules 1210(3) and 1229(17)
	R 408.41236	The hazards associated with the rescinded rules will be addressed by Rules 1210(3), 1217(1), and 1219(2).
	R 408.41237	The hazards associated with the rescinded rules will be addressed by Rules 1210(3) and 1213(3).
	R 408.41243	The hazards associated with the rescinded rules will be addressed by Rules 1243(2), 114(2) and 123.
	R 408.41244	The hazards associated with the rescinded rules will be addressed by Rules 114(2) and 115(2)(a).
	R 408.41245	The hazards associated with the rescinded rule will be addressed by Rule 114(2).
	R 408.41246	The requirement for operator training will be addressed by Part 13, Mobile Equipment.

CS Part 12 Scaffold and Scaffold Platforms has Been Amended Due to the ARC Report to ORR

STANDARD	RULE NUMBERS	MIOSHA IMPLEMENTATION STRATEGY
	R 408.41253	The hazards associated with the rescinded rules will be addressed by Rules 1210(3) and 1217(7).
	R 408.41254	The rules for carpenter bracket scaffolds were amended to the OSHA equivalent.
	R 408.41255	The hazards associated with the rescinded rules will be addressed by Rules 1210(3) and 1217(1).
	R 408.41256	The hazards associated with the rescinded rules will be addressed by Rules 1210(3), 1217(1) and 1217(5).
	R 408.41261	The hazards associated with the rescinded rules will be addressed by Rules 1210(1), 1210(3), 1261(1), 1229(18) and 834(4).
	R 408.41262	The hazards associated with the rescinded rules will be addressed by Rules 114(2)(c), 1210(3), and 1210(6).
	R 408.41263	The hazards associated with the rescinded rules will be addressed by Rules 114(2)(c), 1210(3), and 1210(6).
	R 408.41264	The hazards associated with the rescinded rules will be addressed by Rules 1210(3) and 1213(1).
	Appendix A	A new appendix was added to be equivalent to OSHA.